
FIG. 1  
PRIOR ART

FIG. 2

CLAMP CASE	Op1>=	Op2>=	Op1 LEADING ZEROS	Op2 LEADING ZEROS	TOTAL LEADING ZEROS
45a	1. 0.100000.0000	0.000010.0000	0	4	4
45b	2. 0.010000.0000	0.000100.0000	1	3	4
45c	3. 0.001000.0000	0.001000.0000	2	2	4
45d	4. 0.000100.0000	0.010000.0000	3	1	4
45e	5. 0.000010.0000	0.100000.0000	4	0	4

FIG. 3




FIG. 4




FIG. 5




FIG. 6